



St George's Church Great Bromley

Parish of The Bromleys

Repair to the Stone Family Window in the North Aisle

A small area of the left-hand lower scene had been damaged. Auravisions Ltd of Ashdon, near Saffron Walden, removed the damaged part and created a replacement, which was installed on 28th July 2022, by their conservator, Susan. She also cleaned a tiny area of that part of the window with a clean white cloth.

Auravisions will be quoting to survey and clean all the windows on the ground floor of the church, which was probably last done in the 1960s. This survey and expert clean is our current project.


Here is the Stone Window in the north aisle, before repair:



A close-up of the damaged area,
taped over:



This is the repaired scene:



We are delighted with the result and are happy that the black patch over the hole in the window has now gone.

Here is a shocking photograph. Susan used a white cloth to wipe the boat sail in the background of this photograph. It is not a large area of the window and yet, look at what a superficial clean produced.



Cleaning leaded quarries of stained glass is painstaking work. If you would like to contribute to [St George's Great Bromley Repair Fund](#) to help with our ongoing conservation and restoration work, click on the link. Any help you can give is much appreciated.

Thank you for your support.

G. Frostick
3rd August 2022